

FIELD INSPECTION

			,
Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Monday, November 26, 2018	Project Contact:	Brian Clauto
Spread: Roanoke County MP243 St#12867-12865	Spread H	Weather (Wet/Dry/Rain):	Wet
STAGE OF CONSTRUCTION: (Check all that apply)			
Clearing	Rough Grading	Trench Excavation	Pipe Assembly, Testing & Installation
Backfilling and Grade	e Restoration Final Grading	& Stabilization	Other: Bore pit
	d and implemented in accordance with the		
erosion and sedimei Are all control meas	nt control plan and stormwater managem- ures properly maintained in effective oper ince with good engineering practices and, turer specifications?	rating	
3 Areas of offsite sedi	ment deposition were observed?		
Comments: St#12867+08 - S	t#12865+11 all work being condu	cted was within the LOD	no construction was being
 St#12867+08 – St#12865+11 all work being conducted was within the LOD, no construction was being conducted within the designated wetlands. Torn silt fence was observed at St#12865+11 			
Recommended Corrective Action: replace and maintain all controls per the annual standard and specs.			
<u>Deadline:</u> Within 24hr notification			
The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.			
Inspector Signature: Date: 12-11-18			



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline Date: Monday, November 26, 2018

Fig. 1



Fig. 2 Dewatering structure in place and functioning at the Bottoms Creek bore pit.

North Elevation



• Fig. 3 Work within the LOD of the Bottoms Creek bore pit.



Fig. 4 Wetland perimeter at St#12867+64

